

Turbine Series

Steel Mounting Brackets



Effective November 2009, Racor will change the material used on Ring Clamp style body mounting brackets on all 900 and 1000 Turbine Series aftermarket units. This will include dual (73, 75) and triple (77, 79) models as well. The change will be from aluminum to carbon steel. The black (FH models) and white (marine MA models) color coatings will remain the same.

Dimensionally, the steel versions are identical and are 40% stronger. Underwriters Laboratories, Inc. has tested and approved them for use on all marine listed (MA) models. There is no cost increase to the customer for this material change.



Contact Information

Parker Hannifin Corporation
Racor Division
P.O. Box 3208
3400 Finch Road
Modesto, CA 95353

phone 800 344 3286
209 521 7860
fax 209 529 3278
racor@parker.com

www.parker.com/racor
www.parker.com/racorproducts

Product Features

- Greater than 40% Increased Strength
- Underwriters Laboratories, Inc. Tested
- UL Marine Listed, MQ397
- Coatings and Dimensions are Unchanged
- More Robust and Durable

Service Kits (includes fasteners)

- RK11-2005 (single black steel bracket kit)
- RK11-2006 (single white steel bracket kit)
- RK11-2007 (dual black steel bracket kit)
- RK11-2009 (dual white steel bracket kit)



ENGINEERING YOUR SUCCESS.

DISTRIBUTED BY:



***BOLLAND
MACHINE***

A DIVISION OF DIESEL ENGINE PARTS WAREHOUSE INC.

**Contact Us for Product Information
or to Place an Order**

Phone 724-846-1290

Fax 724-846-5253

Email *kevin@bollandmachine.com*

Address 2718 Darlington Road
Beaver Falls, PA 15010

www.bollandmachine.com